




Case Study | Hazardous waste incinerator in Southeast Texas



*A lifespan of 2-3 times
longer than previous
assemblies.*

Problem:


Thermocouples and thermowells in secondary combustion chamber were failing due to the effects of chlorine and sulfur.

Solution:

Thermo Sensors suggested using a high nickel alloy material for the thermowells and proprietary thermocouples using different construction method.

Result:

The new thermowells and thermocouples are lasting 2-3 times longer than previous assemblies.



PREMIER TEMPERATURE MEASUREMENT PRODUCTS

972.494.1566 1.800.889.5478

thermosensors.com