


Case Study | Refinery in Southeast Texas



*Constant readings and
no drift after eight years
of service.*

Problem:

RTDs on gasification unit were “opening up” and showing inconsistent temperature readings among 3 RTDs in same area.

Solution:

Installed Thermo Sensors’ “Reliatemp” RTDs with guaranteed insulation resistance.

Result:

RTDs have been in service for over eight years with no drift and consistent readings on all three RTDs.



PREMIER TEMPERATURE MEASUREMENT PRODUCTS

972.494.1566 1.800.889.5478

thermosensors.com